



KL-1380-7533 / KL-1380-7535

Crankshaft Sealing Ring Assembly Tool /
Crankshaft Counterholding Spanner



Product information

 Read and understand before use!

EN



www.gedore-automotive.com



GEDORE Automotive GmbH

Breslauer Straße 41
78166 - Donaueschingen
Postfach 1329
78154 Donaueschingen - GERMANY

☎ +49 (0) 771 / 8 32 23-0
☎ +49 (0) 771 / 8 32 23-90
✉ info.gam@gedore.com
🌐 gedore-automotive.com

GEDORE TOOLS, INC.

Only for USA, Canada & Mexico / Sólo para EE.UU., Canadá y México
Seulement pour les USA, le Canada et le Mexique
7187 Bryhawke Circle, Suite 700
North Charleston, SC 29418, USA

☎ +1-843 / 225 50 15
☎ +1-843 / 225 50 20
✉ info@gedoretools.com
🌐 gedore.com

Product description

KL-1380-7533 - Crankshaft sealing ring assembly tool

Suitable for Citroen, Opel, Peugeot, and Toyota 1.0 + 1.2 (3-cylinder) petrol engines. Installed, for example, in Citroën Berlingo III, Berlingo IV, C-Elysee, C1 II, C3 Aircross, C3 III / C3 Picasso, C3 IV, C4 Cactus, C4 II, C4 Picasso/Grand Picasso, C4 Space Tourer/Grand Space Tourer, C5 Aircross, DS3 / DS3 Convertible, DS4; Peugeot 108, 2008, 208, 3008, 301, 308, 5008, 508, Partner IV, Rifter; Toyota Aygo; Opel Combo-E, Crossland X, Grandland X, etc. Engine codes: 1.0 engines: EB0 (ZMZ), EB0F (ZMZ); 1.2 engines: 1PP (HM01), EB2 (HMV), EB2 (HMZ), EB2ADT (HNP), EB2ADTD (HNK), EB2ADTS, EB2ADTS (HNS), EB2ADTX (HNN), EB2D (HMT), EB2DT (HNZ), EB2DTM (HNV), EB2DTS (HNW), EB2DTS (HNY), EB2DTS (HNN), EB2F (HMZ), EB2M (HMY)

Alternative tools: 0109-3, EN-52133 .

For professional and damage-free forcing in of the crankshaft sealing ring (on the timing belt side). Required, for example, when changing the timing belt or repairing the engine.

Recommended accessories:

KL-1380-753 KB - Locking tool kit, PSA 1.0 + 1.2

KL-1380-754 K - Locking test tool set PSA 1.2 GDI



Scope of supply/component overview

Item	Part no.	Description	Qty.
-	KL-1380-7533	Crankshaft sealing ring assembly tool	1

Specifications

For engine type:.....Petrol



⚠ Safety instructions and regulations

- ✔ **Prior to each use** of the special tools, read and understand all safety instructions and **follow** them for **safe use**!
- ✔ Use the special tools **as intended** and **always** carry out maintenance and repair work in compliance with the regulations on occupational safety and accident prevention as well as the vehicle manufacturer's instructions!
- ✔ **Prior to each use**, check the special tools **carefully** for damage, loose parts or unauthorised modifications. **Never** use it if you notice any such deficiencies!
- ✔ **Always** wear your personal protective equipment (for example safety goggles, protective gloves, safety shoes) when working!

Product description

KL-1380-7535 - Crankshaft counterholding spanner

Suitable for Citroën, Opel, Peugeot, and Toyota 1.0 + 1.2 (3-cylinder) petrol engines. Installed, for example, in Citroën Berlingo III, Berlingo IV, C-Elysee, C1 II, C3 Aircross, C3 III / C3 Picasso, C3 IV, C4 Cactus, C4 II, C4 Picasso/Grand Picasso, C4 Space Tourer/Grand Space Tourer, C5 Aircross, DS3 / DS3 Convertible, DS4; Peugeot 108, 2008, 208, 3008, 301, 308, 5008, 508, Partner IV, Rifter; Toyota Aygo; Opel Combo-E, Crossland X, Grandland X, etc. Engine codes: 1.0 engines: EB0 (ZMZ), EB0F (ZMZ); 1.2 engines: 1PP (HM01), D12XHL, D12XHT, EB2 (HMT), EB2 (HMW), EB2 (HMZ), EB2ADT, EB2ADT (HNP), EB2ADT (HNP) / LES / D12XHT, EB2ADT / LES, EB2ADTD, EB2ADTD (HNK), EB2ADTS, EB2ADTS (HNS), EB2ADTS (HNS) / LES / D12, EB2ADTS (HNS) / LES / D12XHT, EB2ADTS / LEG, EB2ADTX, EB2ADTX (HNN), EB2D (HMU), EB2DT (HNV), EB2DT (HNX), EB2DT (HNZ), EB2DT / LES, EB2DTM (HNV), EB2DTS (HNW), EB2DTS (HNY), EB2DTS / LEG, EB2DTS / LES / B12XHT, EB2DTSD (HNX), EB2DTSM (HNW), EB2F (HMT), EB2F (HMX), EB2F (HMZ), EB2F / LEZ, EB2FA (HMR), EB2FA / LEZ, EB2FAD (HMH), EB2FAD (HMM), EB2FB (HMP), EB2FD (HMU), EB2M (HMY), EB2M (HMY), HN02.

For professional counterholding of the crankshaft when loosening and tightening the central crankshaft bolt. Required, for example, when changing the timing belt or repairing the engine.

Required accessories:

KL-1780-1501 A - Lever

Recommended accessories:

KL-1380-753 KB - Locking tool kit, PSA 1.0 + 1.2

KL-1380-754 K - Locking test tool set PSA 1.2 GDI




Scope of supply/component overview

Item	Part no.	Description	Qty.
-	KL-1380-7535	Crankshaft counterholding spanner	1

Specifications

For engine type: Petrol



GEDORE-Werkzeugfabrik GmbH & Co. KG

Remscheider Straße 149
42899 - Remscheid
Postfach 120361
47873 Remscheid
GERMANY

Vertrieb DEUTSCHLAND

☎ +49 (0) 2191 / 596-0
☎ +49 (0) 2191 / 596-230
✉ info@gedore.com
🌐 www.gedore.com

Sales INTERNATIONAL

☎ +49 (0) 2191 / 596-910
☎ +49 (0) 2191 / 596-911
✉ info@gedore.com
🌐 www.gedore.com

GEDORE TOOLS, INC.

Only for USA, Canada & Mexico
Sólo para EE.UU., Canadá y México
Seulement pour les USA, le Canada et le Mexique
7187 Bryhawke Circle, Suite 700, North Charleston, SC 29418, USA

☎ +1-843 / 225 50 15
☎ +1-843 / 225 50 20
✉ info@gedoretools.com
🌐 www.gedoretools.com

Worldwide GEDORE service centers and offices are listed on the Internet at: www.gedore.com

GEDORE Automotive GmbH

Breslauer Straße 41
78166 - Donaueschingen
Postfach 1329
78154 Donaueschingen
GERMANY

Vertrieb DEUTSCHLAND

☎ +49 (0) 771 / 8 32 23-0
☎ +49 (0) 771 / 8 32 23-90
✉ info.gam@gedore.com
🌐 gedore-automotive.com



www.gedore-automotive.com